

Spring 2005

## **Rotor Replacement Parts OEM Quality. Lower Prices.**

J&L now offers rotor replacement parts for Black Clawson screen models 12P, 24P, 24PS/PH, and UV100-500. J&L guarantees the same quality and workmanship at a fraction of the OEM price. Improve your maintenance budget, call J&L today!

***It is highly recommended to replace all foils on the rotor hub to maintain balance and superior performance.***

Lead-time is 2-3 weeks on the following items.

### **12P Screen**


- 083-0012-001 Rotor Foils (Qty 4)
- 083-0012-002 Rotor Hub and 4 Foil Assemblies
- 083-0012-003 End Face Seal Assembly

### **24P Screen**

- 083-0012-004 Rotor Foils (Qty 4)
- 083-0012-005 Rotor Hub and 4 Foil Assemblies
- 083-0012-003 End Face Seal Assembly

### **24PS/PH Screen**

- 083-0012-007 Rotor Foils (Qty 4)
- 083-0012-008 Rotor Hub and 4 Foil Assemblies
- 083-0012-009 End Face Seal Assembly



Lead-time is 5-6 weeks on the following items.

### **UV 100 Screen**

- 083-0012-012 Rotor Foils (Qty 4)
- 083-0012-013 Rotor Hub and 4 Foil Assemblies

### **UV 200 Screen**

- 083-0012-014 Rotor Foils (Qty 4)
- 083-0012-015 Rotor Hub and 4 Foil Assemblies

### **UV 300 Screen**


- 083-0012-011 Rotor Foils (Qty 4)
- 083-0012-010 Rotor Hub and 4 Foil Assemblies

### **UV 400 Screen**

- 083-0012-016 Rotor Foils (Qty 4)
- 083-0012-017 Rotor Foils (Qty 6)
- 083-0012-018 Rotor Hub and 4 Foil Assemblies
- 083-0012-019 Rotor Hub and 6 Foil Assemblies

### **UV 500 Screen**

- 083-0012-020 Rotor Foils (Qty 4)
- 083-0012-021 Rotor Foils (Qty 6)
- 083-0012-022 Rotor Hub and 4 Foil Assemblies
- 083-0012-023 Rotor Hub and 6 Foil Assemblies



**J&L Fiber Services, Inc.**  
809 Philip Drive  
Waukesha, Wisconsin 53186  
U.S.A.  
Phone: 262-544-1890  
Fax: 262-547-8166  
[www.jlfiberservices.com](http://www.jlfiberservices.com)